

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20215737, Public Works Right of Way Permit Address: 1518 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Matt Munger Passed Monday, November 22, 2021

Corrective Action Required

1 Misc Site Visit - The drop has been installed.

Comments: