

Alpha Omega Geotech, Inc 1701 State Avenue Kansas City, KS 66102 Phone: 913-371-0000

Masonry Inspection Report

Client: Project:

LSPH Investors, LLC

7939 Floyd Street Chipotle Lee's Summit Overland Park, KS 66204 1130 SE Oldham Pkwy Lee's Summit, MO

21-390F

Activity Date: 11/19/2021 Technician: Marquez, Jeff

Time In: 12:30 Time Out: 14:30

Temperature (F): 47 Weather: Partly Cloudy

GENERAL OBSERVATIONS

Location of Masonry Inspected: Dumpster enclosure @ 4ft

Plans Used: Structural Drawing No.: SP 102/7

Supporting System (Specify): Na

Straight: Yes Clean: Yes Tied & Clipped: N/A

Proper Lap Length Per Plan: Yes

Rebar Displaced During Grout Placement: No

Grout Temp (F): 65 Mortar Temp (F): 63

Test specimens: Prisms

FIELD OBSERVATIONS

Masonry Joints Per Plan: N/A Control Joint Spacing: N/A

How many feet?: Na

Bond Beams Placed Per Plan: N/A Elevation Of Continuous Beam: Na

Lintels Installed Over /openings: N/A

Duro Wall Placed Per Plan: Yes **Speed Wire Placed Per Plan:** Yes

Bearing Plates Per Plan: N/A Bulb Tees Per Plan: N/A

Are There Non-Compliance Items: No