



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20210092, Public Works Right of Way Permit
Address: 1521 SW SUGAR TREE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Tuesday, November 30, 2021

Corrective Action Required

1	Misc	Site Visit - The line has not been buried yet. I have reached out to ECC. Monitoring.
---	------	---

Comments: