CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211353

Address: 4820 NE JAMESTOWN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Tuesday, November

Residential 30, 2021

Corrective Action Required:

1 Misc -Nail corner studs per code at front bedroom

-Toe nail all joists to wall top plates per code

- -Fb floor penetrations at traps
- -Complete electrical to exterior garage lights -Provide triple joists above garage per plan
- -Install anchor washers and nuts at garage PFH wall
- -Complete framing at fireplace and secure fireplace to framing
- -Complete electrical at fireplace
- -Solid block ends of Isl rafters above great room Ivl beam
- -Pan off return air at 2nd fl bathroom tub
- -Brace ends of IvI roof beam from rotation
- -Provide a smoke/CO alarm immediately outside the bedrooms area
- -Nail siding at step flashings
- -Provide attic access to upper roof space
- -Have engineer check beam size underneath the master bedroom/fireplace
- -Anchor sill plate within 12" of basement slide door
- -Toe nail basement joists to sill plates per code
- -Joist notched more than 1/6 joist depth below front bath tub

**DO NOT INSULATE

Comments: