

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20211374  
Address: 1917 NE CATALINA AVE, LEES SUMMIT, MO 64064

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Khanh Nguyen	Failed	Wednesday, December 01, 2021

Corrective Action Required:

1	Misc	-Nail the garage wall siding at front to sill plates @6" oc
		-Fb the fireplace space from master bedroom ceiling soffit with 3/4" sheathing or fiberglass ** send me a picture when you are done. The sheathing used for fire blocking at soffit wall is 7/16". Should use 3/4" nominal sheathing or just fill in the soffit wall with insulation

**\*\*OK TO ROCK**

**Comments:**