

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #:PRPWRW20215998, Public Works Right of Way Permit Address: 1600 SW BUCKTHORN ST, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Matt Munger Partial Monday, December 06, 2021

Corrective Action Required

1 Misc Site Visit - No workers onsite. One Spectrum vault has been

installed the NW corner of Buckthorn. Will continue to monitor

work.

**Comments:**