CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211430

Address: 134 NW JOSHUA DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Patrick Schonfeldt Not Ready Wednesday, December

Residential 08, 2021

Corrective Action Required:

1 Miscellaneous : PFH PORTAL FRAME ONLY :

Correction 5/8 ANCHOR BOLTS SHALL LAND IN MIDDLE 1/3 THE WIDTH OF PLATE

OVER NOTCHED STUDS AT 5/8 ANCHOR BOLTS

Corrective Action Required:

2 Misc - 12/8/21 - INSPECTION DENIED, ADDRESS EROSION CONTROL AT FRONT OF

LOT, CLEAN ALL MUD AND GRAVEL FROM STREET/CURB

-nail exterior sheathing per plan

-Attic access requires 30" of clearance above

-Protect nm at top plate near range less than 1.25" to face of stud

- address over notched studs at 5/8" anchor bolt between garage doors

Comments: