



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20210287, Public Works Right of Way Permit  
Address: 1513 SW SUGAR TREE DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

|                              |             |          |                             |
|------------------------------|-------------|----------|-----------------------------|
| Inspection:                  | Inspector:  | Outcome: | Date:                       |
| <b>Site Visit Inspection</b> | Matt Munger | Passed   | Thursday, December 09, 2021 |

Corrective Action Required  
1      Misc      Site Visit - GF drop complete.

**Comments:**