



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20215998, Public Works Right of Way Permit  
Address: 1600 SW BUCKTHORN ST, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Partial	Monday, December 13, 2021

**Corrective Action Required**

1	Misc	Site Visit - No workers onsite. Their equipment has been staged and they have installed Spectrum pedestals throughout the subdivision. By the markings on the pavement, they are meeting the city requirements for boring under the roadways.
---	------	---

**Comments:**