

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20202637  
Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Robb Popp	Partial	Thursday, December 16, 2021

Informational:

1	FIRST FLOOR	**AREAS APPROVED**  -SHAFT LAYER AT BUILDING A/B SEPARATION WALL BOTH SIDES -SCREW PATTERN AND FIRE TAPE SHAFT WALL BUILDING A -SHAFT LAYER AT BUILDING C/D SEPARATION WALL -SCREW PATTERN AT SHAFT WALL BUILDING C -SHAFT LAYER AND SCREW PATTERN AT SECOND LAYER ELEVATOR BUILDING B -SHAFT CEILING RATING AT A11, A14, -SCREW PATTERN 2ND LAYER C113,C111,C111A
---	-------------	--

Corrective Action Required:

2	Miscellaneous Correction
---	-----------------------------

Corrective Action Required:

3	SECOND FLOOR	-SHAFT WALL LAYER AT BUILDING A -BETWEEN FLOOR SEPARATION AT BUILDING A/B SHAFT WALLS -SHAFT LAYER AT MECHANICAL/ PLUMBING CHASES ROOMS A218,A214, -SHAFT CEILING RATING AT A26, A25 -SHAFT LAYER AT CHASE B211, ,C213, C209 -SHAFT WALL BETWEEN C&D-SCREW PATTERN OK
---	--------------	--

**Comments:**