



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20212997, Public Works Right of Way Permit
Address: 1909 NE PARK RIDGE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection		Passed	Thursday, December 16, 2021

Corrective Action Required	
1 Misc	GF drop complete passed

Comments: