



Proofroll Inspection Report

Alpha Omega Geotech, Inc
1701 State Avenue
Kansas City, KS 66102
Phone: 913-371-0000

Client:
LSPH Investors, LLC
7939 Floyd Street
Overland Park, KS 66204

Project:
21-390F
Chipotle Lee's Summit
1130 SE Oldham Pkwy
Lee's Summit, MO

Activity Date: 12/17/2021

Technician: Marquez, Jeff

Time In: 08:00

Time Out: 09:00

Temperature (F): 38

Weather: Partly Cloudy

GENERAL OBSERVATIONS

Proofroll Observations:

I was asked to observe a proof roll on the parking lot North of the building a fully loaded tandem axle dump truck weighing approximately 50000 pounds ran across the area with significant pumping and rutting at a 70' long area just North of bldg.

Visual Proofroll Acceptance: No

If Yes, Please Explain: Na

Source Of Fill (If Applicable): Na

Visual Description Of Subgrade: Dark brown soft clay

Are There Non-Compliance Items: Yes



Project:

21-390F
Chipotle Lee's Summit
1130 SE Oldham Pkwy
Lee's Summit, MO

Discrepancy Description: Failed proof roll