CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20202637 Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspectio	in:	Inspector:	Outcome:	Date:
Hood/Du	ct Inspection	Robb Popp	Partial	Tuesday, December 21, 2021
Informati	onal:			
1		Grease duct in G108: -Light test OK		

-1st layer wrap ok

Comments: