



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20203026, Public Works Right of Way Permit  
Address: 1853 SW BLACKSTONE CT, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Passed	Wednesday, January 12, 2022

Corrective Action Required  
1      Misc      Site Visit - GF drop complete.

**Comments:**