

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20203023, Public Works Right of Way Permit Address: 1829 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Matt Munger Passed Wednesday, January 12, 2022

Corrective Action Required

1 Misc Site Visit - GF drop complete.

Comments: