

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20212780
Address: 1921 NE CATALINA AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Tuesday, January 25, 2022

Corrective Action Required:

- | | | |
|---|------|--|
| 1 | Misc | -Provide wall receptacle spacing per code at rear kitchen exterior wall
**At any point along the wall, there shall be a wall receptacle located within six ft |
| | | -Anchor garage PFH walls per code
**no good |
| | | -Provide wall receptacle spacing per code 2nd fl loft
**At any point along the wall (Note: a guardrail on the perimeter of the loft is considered a wall space), there shall be a wall receptacle located within six ft |
| | | -Secure and support the hot tub circuit at max 4.5 ft interval |

Comments: