

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20212780
Address: 1921 NE CATALINA AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Patrick Schonfeldt	Failed	Thursday, January 27, 2022

Corrective Action Required:

1	Misc	-post site address -seal through floor penetration of ward flex at fireplace -seal bottom and top plate penetrations at AC line kitchen wall -seal bottom plate penetrations at NM master shower -Gas line bond required
---	------	--

Comments: