



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20212431, Public Works Right of Way Permit
Address: 111 NW JOSHUA DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Nick Scott	Passed	Friday, January 28, 2022

Corrective Action Required	
1 Misc	Site Visit - The line has not been installed yet.
Corrective Action Required	
2 Misc	Site visited and gas line is still not installed
Corrective Action Required	
3 Misc	Site visited and it appears gas is connected. Passed

Comments: