



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20215992, Public Works Right of Way Permit

Address: 408 NW OLIVE ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection		Passed	Monday, February 07, 2022

Corrective Action Required

1	Misc	Site visited and it appears that gas has been installed off marks on pavement. Passed
---	------	---

Comments: