

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20202637  
Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>In-wall Inspection</b>	Robb Popp	Partial	Tuesday, February 08, 2022

Informational:

1 FIRST FLOOR

**\*\*BUILDING A:**  
-COMPLETE

**\*\*BUILDING B:**  
-COMPLETE

**\*\*\*BUILDING C:**  
-COMPLETE EXCEPT FUR OUTS  
-C109

**\*\*\*BUILDING D:**  
-EAST OF CUMN LINE G OK

**\*\*\*BUILDING E:**  
-DWV FOR BATHROOMS 123, 124,104B,105,108,107b  
-STORM DRAIN AT 110,111  
-D 100A-100C

**\*\*\*BUILDING F**  
-PLUMBING FOR DRINKING FOUNTAIN VESTIBULE F102, f104A-B  
-DWV FOR RESTROOMS 104AM 104B

-SCOREBOARD WALL F104

\*\*BUILDING G

-PLUMBING FOR BATHROOMS 108C, 108D

-DWV AT BLOCK WALLS IN SERVERY AND AL A CARTE G102,103, G108, G101

Informational:

2 SECOND FLOOR

\*\*BUILDING A:

- COMPLETE

\*\*BUILDING B

-COMPLETE

\*\*BUILDING C

-COMPLETE

**Comments:**