



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20220117, Public Works Right of Way Permit
Address: 114 NW GRADY CT, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Nick Scott	Partial	Thursday, February 10, 2022

Corrective Action Required	
1 Misc	Site visited and it appears work has started and it appears. No workers are on site.

Comments: