


BOB D. CAMPBELL & CO.
Structural Engineers Since 1957
4338 Belleview Ave. 816.531.4144
Kansas City, MO 64111 www.bdc-engrs.com

PRINCIPALS

President
Michael J. Falbe, P.E.

Steven R. Carroll, P.E.
Richard C. Crabtree, P.E.
Wayne E. Davis, P.E.
Jeffrey L. Wright, P.E.
Christopher W. Boos, P.E.
Clark A. Basinger, P.E.
Brandon M. Ford, P.E.
Christopher A. Beverlin, P.E.

Administrative Manager
Paul M. Spena

February 4, 2022

Mr. Alan Rust
Twisted Fresh

Re: Twisted Fresh
West Pryor

Dear Alan:

As requested, I visited the site on February 4, 2022 to review the penetrations in the floor for tenant finish work. I have reviewed the penetrations shown in the attached tenant finish document and as shown in the attached photos and have determined the existing floor structure is able to accommodate these openings. No structural remediation is required as a result of these penetrations.

Please call if you have any questions or if we may be of further service.

Sincerely,

BOB D. CAMPBELL & CO.
Structural Engineers



Clark A. Basinger, P.E., Principal

cc: File / TRI1806







