

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211211

Address: 628 NW WILLOW DR, LEES SUMMIT, MO 64081626 NW WILLOW DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Michael Harkins	Failed	Friday, February 11, 2022

Corrective Action Required:

1	Miscellaneous Correction	626 & 628
---	--------------------------	-----------

Seal all upward penetrations garage mechanical room
Provide 2 layers 5/8 type x garage wall we between units including attic to roof deck @ 2 hour Rated wall assembly inspection required each layer
Expose ceiling 3 season room & front porch to inspect rafters & ceiling joist
Seal upward penetrations 3 season room
Secure & seal gas line at fireplace
Provide bath exhaust fans
Provide Dbl 2 x 10 ridge above garage per roof framing plan
Provide 100 watt flood light rear yard

628
Provide minimum 10 psi on gas line
Provide solid blocking at exterior wall sheathing breaks in kitchen & nail per code

Comments: