# CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

# **DEVSERVICES.CITYOFLS.NET**

# **Inspection Summary**

Permit #: PRCOM20191614

Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes Robb Popp Failed Friday, February 11,

Commercial 2022

## Corrective Action Required:

1 Miscellaneous Correction

TCO has not been issued on this project. See separate divisions for other reports from Fire, Water, Planning, Engineering.

Building is not to be occupied by sales team or open to the public for walk

throughs until a TCO has been issued.

Please contract the Project Manager for further questions.

- -Complete all items for all other departments
- -Submit missing Special inspections final inspection report , see plan review comments when permit was issued.
- -Provide Health Dept approval from Jackson County.
- -Complete all sight lighting and receptacles at lights
- -Backfill at open trenches for electrical
- -Missing vent covers at NW exterior
- -Hood system not approved-Gas to remain off until approved
- -Open public street for access
- -5 LB Max force to open all egress doors
- -Roofs-Label all units, AC disconnect need labeled & missing covers, GFCI proteced receptacles, secure whips within 12"-WORKING ON ELECTRICAL AT TIME OF INSPECTION
- -Pool equipment room-Reconnect bond wire
- -Pool- complete drinking fountain installation, missing accessible bathroom

signs, mirrors are not ADA compliant

- -Complete electrical at corridor to kitchen
- -All hard piped appliances require back flow devices- ice/water maker, coffee machine, soda dispenser etc.
- -Secure electrical panel covers at kitchen
- -Correct gaps greater than 4" at 2nd floor gaurdrail
- -Paint all exterior metallic gas lines with corrosion preventitive paint

2042 - permanent sign, grab bar behind toilet max 6" gap from side wall

2045- Signage at electrical room door per nec 110, seal penetrations at lineset, ductwork and conduit

2047-Seal behind riser, screw fire collar

1002- loose receptacle at washer, secure diswaher discharge line above sink,

1004- GFCI protection at dishwasher-LOCKED AT FINAL

1007 clean paint from sprinkler head and install eschucheon-NOT DONE AT FINAL

1008- complete discharge and water at dishwasher, secure exterior gfci box and seal perimeter, address storm discharge, grab bars-NOT DONE AT FINAL 1019-secure dishwasher discharge above bowl of sink-NOT DONE AT FINAL 1025-spark rings at all kitchen receptacles, hardware on sliding glass door,\_NOT DONE AT FINAL

1024-spark rings & cover plate kitchen counter -NOT DONE AT FINAL 1023 - GFCI protection at kitchen counter receptacle left of sink, ADA unit/install grab bars, kitchen sink accessibility, -NOT DONE AT FINAL

1038-Complete condensate line

1053 incomplete

1046-1047-Permanent accessible signs

1045-Seal penetration at dwv to hallway

## **Comments:**