CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20213123

Address: 130 NW JOSHUA DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Failed Monday, February 14,

Residential 2022

Corrective Action Required:

1 Miscellaneous Secure fireplace

Correction Provide 1 roof vent covered patio

Nail studs at intersecting wall corners at braced wall panels

Nail exterior wall sheathing per code Seal DWV AT bottom plate bath 2 Tighten anchor bolts garage & basement

Provide anchor bolts within 12" of plate break north basement wall

Fire block HVAC soffit north basement wall

Provide nut & washer on anchor bolt NW corner basement

Provide solid security blocking patio door basement Seal fire blocking top plate south basement wall Provide vertical fire blocking every 10' bed 4 basement

Fire block soffit above window bed 4

Provide anchor bolts east of window bed 4

Provide flashing above horizontal window trim window under deck

Comments: