



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20211812, Public Works Right of Way Permit  
Address: 114 SE DOUGLAS ST, LEES SUMMIT, MO 64063

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Passed	Tuesday, February 15, 2022

**Corrective Action Required**

1	Misc	Site Visit - It appears the work is completed, if there is further work to be done, another ROW permit will need to be applied for.
---	------	---

**Comments:**