CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20202637 Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Above Ceiling Inspection		Robb Popp	Partial	Thursday, February 10, 2022	
Corrective	e Action Required:				
1	THE FOLLOWING	2 EAST EXTERIOR CANOPIES-OK			
	AREAS ARE APPROVED	NORTH EXTERIOR CANOPY-OK			
		-SOFFITS AT: CLEAR STO	-SOFFITS AT: CLEAR STORY A100, B100A		
		•	-HARD LIDS AT A213, B114, 121A, B113, C100A		
		,,B115,B117,C101A,C10,C C20	,,B115,B117,C101A,C10,C10A,C129,C127,C121,C115D,C102-C104, C208, C214, C20		
		BUILDING A: A111.A112.	BUILDING A: A111,A112,A113, A100A,A100C,,A13,A110B,A101, A103, A104, A105, A106 A108,A108A,A110,A110A,117A,117B,118,118B		
		A202, 203, 204, 205, 207, 208, 209, 210,21,200A,23,24,220A			
		BUILDING B: 101-103, 10	UILDING B: 101-103, 105-108, 110, 110A, 111,112, 117,118, 121, 121C, 122,		
			1-206, 208, 209, 211, 212, 214A, 215, 216, 216A, CORRIDORS EXCEPT AT B10 D AT RATED ASSEMBLIES		
		**B113,B115, B121C, B121D, B122, B121, B121B, B120, B119 B212, B201, E		8 B120 B119 B212 B201 B203	
		B204-OK FOR BORDERS (
		BUILDING C: 101,101A,1	06-109, 111-113, 119, 1	120, 122-126, 128-131, 201-204,	
		211, 212, ,115-115C, 217/	A-217D, 219-219C, ALL	CORRIDORS EXCEPT AT RATED	

ASSEMBLIES

**C102, C104, C115A, C115B, C115C ,C117, C118, C119,C210, C206, C207 OC216, C216B, OK FOR BORDERS ONLY

AREA D

- 1/27/22 HARD LIDS: D103 MEDIA CENTER, D101 A la carte counter, G108D -

AREA G: 102, 103, 107, 108, 108B, 108F OK FOR BORDERS ONLY

Corrective Action Required: Misc

2

A218, A218A- OPEN J BOXES B210- OPEN J BOX B214- OPEN J BOX, EXHAUST HOOD, MISSING (2) TIE WIRES AT MAIN C206,207- COMPLETE FIRE RATED ASSEMBLY AT SEPARATION WALL -SEAL PENETRATIONS, STENCILS AT FIRE SEPARATION WALLS THROUGHOUT CORRIDORS -COMPLETE RATED ASSEMBLIES AT PENETRATIONS, TOP AND BOTTOM AND STENCILS AT VESTIBULES, CORRIDORS, AND ELEVATOR

Comments: