



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20215620, Public Works Right of Way Permit
Address: 119 NW JOSHUA DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Nick Scott	Partial	Wednesday, February 23, 2022

Corrective Action Required

1	Misc	Site visited and it appears that work is done. Grass has been damaged from another utility or by builder I will investigate further.
---	------	--

Comments: