

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20212071  
Address: 4417 SW TANZANITE CIR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Shawn Hoffman	Failed	Friday, March 04, 2022

Corrective Action Required:

1 Misc

- provide proper support for stair landings
- EC#2 800 lb hold down device at master bed corner as noted on plans ( location moved address with engineer)
- 
- address top plate connection 2nd floor stairs 2x6 wall
- all truss lateral bracing per plans
- address floor joist notched at anchor bolt basement at garage wall, min 1 1/2" bearing required for wood
- provide future vent for basement bath group

**Comments:**