

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20212071
Address: 4417 SW TANZANITE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Shawn Hoffman	Failed	Friday, March 04, 2022

Corrective Action Required:

1 Misc

- provide proper support for stair landings
- EC#2 800 lb hold down device at master bed corner as noted on plans (location moved address with engineer)
-
- address top plate connection 2nd floor stairs 2x6 wall
- all truss lateral bracing per plans
- address floor joist notched at anchor bolt basement at garage wall, min 1 1/2" bearing required for wood
- provide future vent for basement bath group

Comments: