

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #:PRPWRW20220117, Public Works Right of Way Permit Address: 114 NW GRADY CT, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Nick Scott Partial Friday, March 25, 2022

Corrective Action Required

1 Misc Site visited and it appears work has started and it appears. No

workers are on site.

Corrective Action Required

2 Misc Site visited and it appears work has not proceeded I will give

them another week and if nothing else has been done i will

email and find out why work has not proceeded.

Corrective Action Required

3 Misc Contacted SCC LLC Underground and they are waiting for

spectrum to finish the work I will come back in a couple weeks

to check on progress

**Comments:**