

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20213052

Address: 3819 SW WALSH DR, LEES SUMMIT, MO 640823817 SW WALSH DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Patrick Schonfeldt	Failed	Friday, March 25, 2022

Corrective Action Required:

1	Misc	-firecaulk electric feeder cable penetration at rated wall rim joist basement -fire rated separation required between units at daylight wall basement R302.3 -repair any damaged sections of fire rock -firerock should be seated in c channel runner at roof deck, no gaps
---	------	---

Comments: