



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20212266, Public Works Right of Way Permit
Address: 4310 SW PRYOR RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Thursday, March 31, 2022

Corrective Action Required	
1 Misc	Site Visit - The work has been completed. Seed/erosion mat has been placed.

Comments: