CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211948

Address: 1928 NE CATALINA AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Sewer Service Inspection - R Khanh Nguyen Passed Wednesday, April 20,

2022

Corrective Action Required:

1 Misc House sewer not connected to the stub due to higher elevation. House

sewer is now connected directly to the wye connection to main. Have Field

Service inspect the wye and abandoned sewer stub

Corrective Action Required:

2 Misc 10-8-21 1:50 AN Spoke with plumber about the issue and he had to install a

new wye, because the existing stub coming out of the main would have been

to high for the sewer coming out of the house.

Corrective Action Required:

3 Misc 10-14-21 AN

-Wye and stub was installed into the main without getting approval from the

citv.

-Need to verify that a trench check and tracer wire was installed.

-contractor abandoned the original stub and it needs to be REMOVED.

-also need the exact location of the new wye between two manholes.

-building sewer stubs being disconnected from the sewer main shall be disconnected by the Water Utilities Department, after the contractor has provided access to the sewer main via an OSHA compliant excavation with

proper shoring as necessary.

Corrective Action Required:

4 Miscellaneous 11-18-21 10:11am AN original sewer stub still has NOT been removed.

Correction

Corrective Action Required:

5 Miscellaneous 4-8-22 AN original sewer stub still needs to be removed. You need to use

Correction max adapters!

Informational:

Misc 4-19-22 AN plumber is at the site and they have began to dig up the sewer

stub so they can abandon it. I did inform them that they need to use max

adapters

Informational:

7 Misc 4-20-22 AN plumber abandoned the the sewer stub and used the max

adapters . Pic attached.

Comments: