## **Inspection Summary**

Permit #:PRCOM20210427, Building Permit - Commercial Address: 250 NW MCNARY CT, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

**Occupancy Inspection** - John A. Jackson Failed **Engineering** 

Corrective Action Required

1 Misc Needed for Temporary Occupancy

1. Accepted As-builts

Needed for For Final Occupancy

- 1. 70% vegetation needs to be established.
- 2. Trash and debris need to be cleaned up.
- 3. Remove silt fence in back of building when vegetation has been established.
- 4. Make sure curb inlet in front of building is cleaned out.
- 5. Dumpster needs to be removed.

**Comments:**