CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20202637 Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Footing Inspection - Commercial		Inspector:	Outcome:	Date:	
		Robb Popp	Partial	Monday, May 16, 2022	
Inform	national:				
1	THE FOLLOWING	**AREA "A"**			
	AREAS ARE	-COMPLETE-			
	APPROVED	**AREA "B"*			
		-COMPLETE-			
		**AREA "C" **			
		-COMPLETE-			
		AREA "D"			
		-COMPLETE			
		**AREA "E" **			
		-COMPLETE			
		AREA G			
		-COMPLETE-			
		AREA F			
		-COMPLETE			
		-Footing and found	-Footing and foundation wall for storage building north of football field		
		-Footing for west monument sign			
		-Footing for East mo	Footing for East monument sign		
		-	Footings for benches 2 East and 3 west		
		-Footing for south a	-Footing for south and north retaining wall east side of building		
		-Footing for learning stairs East sid			

Comments: