

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20212466
Address: 508 SE DAVID RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Shawn Hoffman	Failed	Wednesday, May 25, 2022

Corrective Action Required:

1	Misc	-Pan off fur out and hvac chase with approved materials -Support hip above glue lam -Support hips in double car bay - not easily visible due to plywood but visibly not supported -Support 2x/lvl/glue lam at double car header both sides 5-25-22 - Fire block penetration at RA hallway outside of laundry - Fire block master shower DWV - Land electrical in box and tie wires in master bathroom - Security blocking at sliding door - Open lid of deck roof for inspection - Provide clearance at B vent and ductwork in attic space
---	------	--

Comments: