

## **Third Party Inspection Report**

Inspector	Date	Time			
David P. Ainsworth, P.E.	6-7-22	9:30 AM			
Company	Permit #	Permit Holder			
David P. Ainsworth, P.E.	2022-1554	CLANTON PROPERTIES			
Inspection Type	Address COBRY CREEK LOT 148				
FOOTING	3517 SE CORBIN DR LSMO				
E-Mail Address dainsworth@chelepis.c					
Instructions: This form must be o	ompleted when performing a third p	party inspection for any building			

**Instructions:** This form must be completed when performing a third party inspection for any building permit in Lee's Summit. Submit form within 48 hours after inspection to the Development Services Department. If a subsequent inspection is performed by the City, this form must be submitted prior to that inspection being scheduled.

Check all boxes that apply to the site conditions and the inspection being performed.

A	-	10			
Site	(0)	201	T- 14	nn	C:
JILE	CUI	S COLI	0.89		э.

X	Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable
X	Erosion controls in place and maintained

## **Foundations and Footings:**

X	Foundation type and MBOE is equal to or above the plot plan
X	Concrete encased electrode (ufer) ground installed (Location must be noted in comments)
Bernand .	Foundation/Footing meets all City Code requirements and matches City approved plans or engineered design.

## **Foundation Walls:**

Elevation is sufficient to achieve 2% slope away from structure
No openings below the MBOE
Concrete encased electrode (ufer) ground exposed
Foundation wall meets all City Code requirements and matches City approved plans or engineered design.

<sup>\*</sup>Note: If these requirements are not met no inspection shall be performed or accepted by the City.



Date:						۰				
<b> -</b>	r	a	ľ	٧	Ð	8	P	3	σ	0
	8	u	п	ш	B	u	в	В	Б	8

Framing meets all City Code requirements and matches City approved plans or engineered design.

\*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

## **Corrective Actions and Comments:**

UFER GROUND ROD IS LOCATED IN THE RIGHT SIDEWAY ABOUT 2' BACK FROM THE FRONT RIGHT CORNER.

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.

Signature: Said Clinsworth P.

**Engineer/Architect Seal**