

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

---

Permit #:PRPWRW20221666, Public Works Right of Way Permit  
Address: 2023 SW HOOK FARM DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Partial	Wednesday, June 08, 2022

Corrective Action Required

1 Misc

Site Visit- Norberto had called and stated they had gotten their bore head stuck under the road 2046 SW Hook Farms Dr. I took a picture of where he marked. He stated they were 32-34" under the road. I did remind him of our 36" road crossing depth requirement. I let him know we would need approval before we could give anyone the go ahead to cut the new street. The area has ongoing home builds taking place. Yards have not been established yet. Monitoring work. No workers were onsite.

**Comments:**