

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #:PRPWRW20220033, Public Works Right of Way Permit Address: 1508 SW SUGAR TREE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Matt Munger Passed Wednesday, June 15, 2022

Corrective Action Required

1 Misc Site Visit- The area around the vault has been corrected. This

was also documented/tracked in a SR. Closing. The work was

finished a while ago.

**Comments:**