

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #:PRPWRW20222307, Public Works Right of Way Permit Address: 3904 SW PRYOR RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Matt Munger Partial Thursday, June 16, 2022

Corrective Action Required

1 Misc Site visit - It does not appears gas has started the build in the

newest section of this sub-division. I will check back at a later

time.

**Comments:**