# CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

# **DEVSERVICES.CITYOFLS.NET**

# **Inspection Summary**

Permit #: PRCOM20202637

Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Miscellaneous Inspection Robb Popp Partial Tuesday, June 21, 2022

Corrective Action Required:

L Misc Pre final

### Area A

- -Complete mister for dust collection and provide covers at machine hook ups
- -Provide restroom signage
- -Complete restroom mirrors and access panels
- -Provide all room signage
- -Mechanical room-secure mc at switch, provide cover plates at BMS and at ceiling
- -A108 seal gap outside of electrical outlet at sink,

### A2

- -202,203- cover plates
- -215- remove covers on sprinkler heads
- -206/ cover plates

# В1

- -Provide signage at electrical, label panels and panel schedules throughout
- -Protect gas lines in cabinets at science rooms
- -Ensure 40" to reflective surface at restrooms

- -Secure electrical and complete BMS boxes at mechanical
- -Provide access panel covers at restrooms

B2

# B214 bad gfci receptacles 2 locations

C!

- -Provide all signage and panel schedules at electrical rooms
- -C115D complete shower grab bars
- -Protect in cabinet gas lines at science rooms
- -Install restroom mirrors in gang bathrooms
- -Mechanical room-finish BMS boxes, secure electrical, seal abandoned sleeve in rated wall
- -C105 secure receptacle near mop sink

# **Comments:**