



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20221721, Public Works Right of Way Permit  
Address: 131 NW JOSHUA DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Nick Scott	Partial	Tuesday, June 21, 2022

**Corrective Action Required**

1	Misc	Site visited and it appears that AT&T line still has not been buried. I will email them and get a update on when this will be done. I will come back and check in a couple weeks.
---	------	---

**Comments:**