

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #:PRPWRW20222793, Public Works Right of Way Permit

Address: 1405 SW GEORGETOWN DR, LEES SUMMIT, MO 640821533 SW GEORGETOWN DR, LEES SUMMIT, MO 640824408 SW LODESTONE DR, LEES SUMMIT, MO 640821705 SW HIGHTOWN DR, LEES SUMMIT, MO 640821809 SW HIGHTOWN DR, LEES SUMMIT, MO 640821901 SW HIGHTOWN DR, LEES SUMMIT, MO 640824402 SW AMETHYST DR, LEES SUMMIT, MO 640824401 SW ALABASTER CIR, LEES SUMMIT, MO 640824420 SW ALABASTER CIR, LEES SUMMIT, MO 640824420 SW ALABASTER CIR, LEES SUMMIT, MO 640824421 SW TANZANITE CIR, LEES SUMMIT, MO 640824400 SW TANZANITE CIR, LEES SUMMIT, MO 640824421 SW GRINDSTONE CIR, LEES SUMMIT, MO 640824400 SW GRINDSTONE CIR, LEES SUMMIT, MO 640824400 SW GRINDSTONE CIR, LEES SUMMIT, MO 640821913 SW MERRYMAN DR, LEES SUMMIT, MO 640821937 SW MERRYMAN DR, LEES SUMMIT, MO 640821932 SW HIGHTOWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Matt Munger Partial Thursday, July 07, 2022

Corrective Action Required

1 Misc Site Visit - Steve Hult was onsite (ECC). I spoke with him about

the project and he stated they should be done by today with boring. I did see that they are using a compactor and are using

gravel below the vaults they are putting in.

Comments: