## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20202637 Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Above Ceiling Inspection		Robb Popp	Partial	Wednesday, July 13, 2022
Corrective Action 1 THE FO AREAS APPRO	OLLOWING ARE	BETWEEN C/D; AREA D - 1/27/22 HARD LIDS: D10 G108D - D102, D104, D105, D103, D100, D11,D12 RECEPTIOND14 (Stage Pla AREA E: -E114B, E115, E118, E117 -E10 CORRIDOR HARD LID Area E: E123, E124, E122,	B SOFFITS E101, E102, D103, E104, E1 14A, E117A, E11A,E11B, E1(	01, A la carte counter, .3, SOFFIT AT VESTIBULE 05, E106, E107, E109,

AREA G: 102,103,106,107,108,108B,108F, G109, G108B, G108F, G108, G101, G10A-B, G11,

Comments: