LEE'S SUMMIT

## PUBLIC WORKS ENGINEERING DIVISION

## **Inspection Summary**

Permit #:PRPWRW20222483, Public Works Right of Way Permit Address: 2601 NE MCBAINE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspec	tion Nick Scott	Passed	Wednesday, July 13, 2022
Corrective Action Required1MiscCorrective Action Required			
2 Misc	Misc Site visited and it appears that work is complete and gas has been connected. Passed		

**Comments:**