LEE'S SUMMIT

## PUBLIC WORKS ENGINEERING DIVISION

## **Inspection Summary**

Permit #:PRPWRW20222307, Public Works Right of Way Permit Address: 3904 SW PRYOR RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Monday, July 18, 2022
Corrective Action Requir 1 Misc	Site vis exceed this tin permit	d the minimum depth for s ne. Minimal restoration w	paint marks on the road are street crossings. No issues at ill be needed to close out the lopment where the grass has

**Comments:**