



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20221666, Public Works Right of Way Permit

Address: 2023 SW HOOK FARM DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

| Inspection:                  | Inspector:  | Outcome: | Date:                 |
|------------------------------|-------------|----------|-----------------------|
| <b>Site Visit Inspection</b> | Matt Munger | Passed   | Monday, July 18, 2022 |

**Corrective Action Required**

1      Misc

Site Visit- The installation appears to have been completed. I have tried to reach out to the contractor about the bore head under the road on SW Hook Farm Dr, that they wanted to dig up but that has not started yet. I have not gotten a response back. The bore under the road is being tracked in an SR and will document that work if it takes place in the SR. I am closing this out. A new permit will need to be applied for if further work is going to take place as it has also expired.

**Comments:**