

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20202637  
Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Miscellaneous Inspection</b>	Robb Popp	Partial	Monday, July 18, 2022

Corrective Action Required:

1 Misc

Pre final

Area A

-Complete mister for dust collection and provide covers at machine hook ups

-Provide restroom signage

-Complete restroom mirrors and access panels

-Provide all room signage

-Mechanical room-secure mc at switch, provide cover plates at BMS and at ceiling

-A108 seal gap outside of electrical outlet at sink,

A2

-202,203- cover plates

-215- remove covers on sprinkler heads

-206/ cover plates

B1

-Provide signage at electrical, label panels and panel schedules throughout

-Protect gas lines in cabinets at science rooms

-Ensure 40" to reflective surface at restrooms

- Secure electrical and complete BMS boxes at mechanical
- Provide access panel covers at restrooms

## B2

B214 bad gfci receptacles 2 locations

## C!

- Provide all signage and panel schedules at electrical rooms
- C115D complete shower grab bars
- Protect in cabinet gas lines at science rooms
- Install restroom mirrors in gang bathrooms
- Mechanical room-finish BMS boxes, secure electrical, seal abandoned sleeve in rated wall
- C105 secure receptacle near mop sink

## C2

- Complete BMS and secure electrical
- C208-missing grab bars
- C209-complete electrical and rooftop
- C200A- cover plates
- C219-cover plates
- C217,217A,217B-complete electrical
- C216-complete plumbing
- C215-incomplete

## D

- 101 open boxes for shades at perimeter
- 103 open box for shades
- 108- label panels/schedules
- 110A-complete restroom
- 106- signs at riser room, open j boxes, secure mc, complete electrical

## G

- 05-cut drain 1" above flood level
- 113-cover plate, correct gap at box
- 108D missing mirror
- 107- cover plates at BMS/fire, label panels, schedules

## Comments: