

Third Party Inspection Report

Inspector	Date	Time					
AL HERMANS	4/12/22	1215pm					
Company	Permit #	Permit Holder					
SOC ENGINEERIN	20220622	HNY MIDWEST					
Inspection Type	Address						
FOOTING	# ZOZG SW REL	BARN LANG					
FOOTING A ZOZG SW RED BARN LANGE E-Mail Address alhermanse Sdc-corp-com							
Instructions: This form must be completed when performing a third party inspection for any building							
permit in Lee's Summit. Submit form within 48 hours after inspection to the Development Services							
Department. If a subsequent inspection is performed by the City, this form must be submitted prior to that inspection being scheduled.							
Check all boxes that apply to the site conditions and the inspection being performed.							
Site Conditions:							
Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable)							
Erosion controls in place and maintained							
*Note: If these requirements are not met no inspection shall be performed or accepted by the City.							
Foundations and Footings:							
Foundation type and MBOE is equal to or above the plot plan							
Concrete encased electrode (ufer) ground installed (Location must be noted in comments)							
Foundation/Footing meets all City Code requirements and matches City approved plans or							
engineered design.							
Foundation Walls:							
Elevation is sufficient to achie	Elevation is sufficient to achieve 2% slope away from structure						
No openings below the MBOE	No openings below the MBOE						
Concrete encased electrode	Concrete encased electrode (ufer) ground exposed						
Foundation wall meets all City engineered design.	Foundation wall meets all City Code requirements and matches City approved plans or engineered design.						



F	ra	m	i	n	σ	•
	ıa			, ,	Б	

Framing meets all City Code requirements and matches City approved plans or engineered design.

*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

Corrective Actions and Comments:

UFER IS @ LEFT BASEMENT WALL APPROX. 4 FROM FRONT LEFT CORNER.

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.

Signature/ Engineer/Architect Seal